



VISIBLE EMISSION NOTA	TIONS			•	
Inspector: Stage					
Date of Inspection:	2/1/2		,		
Shift: 1 st Shift or 2 nd Sh	olft Ti	me: 0500			
Unit	Visual		Comments		
	Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL				
Visible Emission From Shaker	N	- A management			
Visible Emission From Discharge Conveyor System	NAL				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	ATIONS		•	
Inspector:	PALONO			
Date of Inspection:	12			
Shift: 1 st Shift or 2 nd Sh	nift Ti 2nd	me: 5:00AM		
Print Unit	Visual		Comments	
	Inspection NORMAL			
	or <u>ABN</u> ORMAL			
Visible Emission From Shaker	NOR	, characteristic consequences constantly.		
Visible Emission From Discharge Conveyor System	100	, martine de la companya de la compa		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS	·
Inspector:) ec	
Date of Inspection:	/ 3/3/12	
Shift: 1 st Shift or 2 nd Sh	ift Ti	ime: Gesto
-First Unit	Visual	Comments
	Inspection <u>NOR</u> MAL or	
	<u>ABN</u> ORMAL	
Visible Emission From Shaker	Nar	, responsibility
Visible Emission From Discharge Conveyor System	Non	pulprishency.

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			
Inspector:	1 /			
Date of Inspection:	4/12			
Shift: 1 st Shift or 2 nd Shi	ft ^r Ti	m(e: 0500		
Unit	Visual		Comments	
	Inspection <u>NOR</u> MAL			
	or <u>ABN</u> ORMAL			
Visible Emission From Shaker	2.4	yanisanine.		
Visible Emission From Discharge Conveyor System	5.9	and the second s		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.





VISIBLE EMISSION NOTATIONS Inspector: ALONC Date of Inspection: 2nd Shift Shift: 1st Shift or Time: Unit Visual Comments Inspection NORMAL or ABNORMAL Visible Emission From Shaker NOR Visible Emission From Discharge Conveyor System NOK

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Inspector:				
Date of Inspection:	٠,		•	
Shift: 1 st Shift or 2 nd Shi	ft Ti	ime:		
Visible Emission From Shaker	Visual Inspection <u>NOR</u> MAL or ABNORMAL		Comments	:
Visible Emission From Discharge Conveyor System				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS		-	
Inspector: Tel Comp	400			
Date of Inspection: 2/7	112			
Shift: 1 st Shift or 2 ^{no} Sh	ift Tir	ime: 500 AM		
Unit	Visual		Comments	
	Inspection <u>NØR</u> MAL			
	or ABNORMAL			
Visible Emission From Shaker	Nor			
Visible Emission From				
Discharge Conveyor System	1) .	,		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			-	-	
Inspector: Ted C	ompton		14			
Date of Inspection: 2/87	120					
Shift: 1 st Shift or 2 nd Sh		me: 500Am				
The work	Visual			Comments		•
	Inspection NORMAL				. :	1 3
	ABNORMAL		1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1		•	•
Visible Emission From Shaker	Nor	And the second s				
Visible Emission From						
Discharge Conveyor System	11/0-	Company of the Compan				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTA	TIONS			·	
Inspector:	Alomo		_		
Date of Inspection: 2 /	10/12				
Shift: 1 st Shift or 2 nd Sh	ift Ti	me: 5:00 Am			
Unit	Visual		Comments		•
	Inspection NORMAL or				
	ABNORMAL		The state of the s	·	
Visible Emission From Shaker	NOR	**PORTED-MANUFACTION AND ADDRESS AND ADDRE			
Visible Emission From Discharge Conveyor System	NOR	**************************************			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			•
Inspector: Smelle Ro	bet		•	
Date of Inspection: Feb 10	12			
Shift: (1 st Shift or 2 nd Sh	ift Ti	ime: 3:00PM		
Umt	Visual		Comments	
	Inspection NORMAL or ABNORMAL			
Visible Emission From Shaker	nor			
Visible Emission From Discharge Conveyor System	nor			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS		-	-	
Inspector:	7				
	nfi on		•		
Date of Inspection: 2/11/	2				
Shift: Shift or 2 sh	ift Ti	ime: 500 AM			
- Unit	Visual		Comments		
	Inspection <u>NOR</u> MAL				
	ABNORMAL		to SV Talingrous		
Visible Emission From Shaker	Nov				
Visible Emission From					
Discharge Conveyor System	No-	All places and the second	us.		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

	VISIBLE EMISSION, NOTA	TIONS			-	
	Inspector:	noton				
	Date of Inspection:	f		······································		
l						
	Shift: 1 st Shift or (2 nd Sh	ift Ti	ime: 500 Am			
	Unit	Visual Inspection <u>NOR</u> MAL Or ABNORMAL		Comments		: .:
	Visible Emission From Shaker	Nor				
	Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS	
Inspector: Ruch A	Land	
Date of Inspection:	12/12	· · · · · · · · · · · · · · · · · · ·
Shift: 1 st Shift or 2 nd Sh	151	Ime: 5,00 PM
Unit	Visual	Comments
	Inspection	
	<u>NØR</u> MAL	
	ABNORMAL	
Visible Emission From Shaker	: \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
Visible Emission From		
Discharge Conveyor System	NOR	magestable stiffing profession for the contract of the contrac

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			
Inspector:	Qea .		,	
Date of Inspection:	2/13/12			
Shift: 1 st Shift or 2 nd Sh	/	me: 0 500		
Unit	Visual		Comments	
	Inspection <u>NOR</u> MAL			1 .:
	or <u>ABN</u> ORMAL			· · · · · · · · · · · · · · · · · · ·
Visible Emission From Shaker	Na	-		
Visible Emission From Discharge Conveyor System	Nac	,		


- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			•	
Inspector:	ACC J				
Date of Inspection:	2/14/	<u> </u>			
Shift: 1 st Shift or 2 ^{na} Sh	jft Tir	me: 6,000			
-Unit	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Comments		
Visible Emission From Shaker	Non	and the set of the set			
Visible Emission From Discharge Conveyor System	Noc				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTAT	IONS		-	
Inspector: 2 CK PA	Lomo			
Date of Inspection: 2/15	Tiz			
Shift: 1 st Shift or 2 ^{ftd} Shift	t' Tir	me: 5:00 AM		
Unit	Visual Inspection <u>NOR</u> MAL Or ABNORMAL		Comments	
Visible Emission From Shaker	NOR	*General medican learner of the control feel medican learner of th		
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTA	TIONS			
Inspector:	omston			
Date of Inspection:	V			
Shift: 1 st Shift or (2 nd)Sh	ift Ti	me: 500AV1		
Unit	Visual Inspection <u>NOR</u> MAL Or ABNORMAL		Comments	
Visible Emission From Shaker	Nor		**************************************	
Visible Emission From Discharge Conveyor System	Nov		And the little was to the litt	

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

١	/ISIR	1 F	FI	VIIS	SIO	N N	COL	ΓΔΊ	IONS	;

Inspector:			
Date of Inspection:	• ,		
Shift: 1 st Shift or 2 nd Shift	Time:		
	Visual Inspection <u>NORMAL</u> or BNORMAL	Comments	
Visible Emission From Discharge Conveyor System			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			•	
Inspector:	į į				
Date of Inspection:	2/18/12		,		
Shift: 1 st Shift or 2 nd Shi	ft Ti	ime: 4 0500			
Unit	Visual Inspection <u>NOR</u> MAL or ABNORMAL		Comments		
Visible Emission From Shaker	Ngl				
Visible Emission From Discharge Conveyor System	aler				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: 2nd Shift Shift: 1st Shift or Time: and a sumit Visual Comments Inspection <u>NÖR</u>MAL or ABNORMAL Visible Emission From Shaker Visible Emission From Discharge Conveyor System NOR

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			-
Inspector:				
Date of Inspection:			,	
Shift: 1 st Shift or 2 nd Sh	lift Th	me: 6',00 6m	·	
Unit	Visual		Comments	-
	Inspection <u>NØR</u> MAL			
	or AB <u>N</u> ORMAL			
Visible Emission From Shaker	2626			
Visible Emission From Discharge Conveyor System	N.			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			
Inspector:				
Date of Inspection:	1/12			
Shift: 1 st Shift or 2 nd Sh	ift) Ti	me: 2 0500		
Unit	Visual Inspection		Comments	
	<u>NOR</u> MAL			
	or <u>ABN</u> ORMAL		to divine Telapyre e	
Visible Emission From Shaker	Nor	(Valentinininini		:
Visible Emission From Discharge Conveyor System	Nor	_		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

AISIBEE EINISSION NOTATI	10113
Inspector:	
Date of Inspection:	* 3

Shift: 1 st Shift or 2 nd Sh	ift Tir	ne:		
Junit	Visual Inspection <u>NOR</u> MAL or ABNORMAL		Comments	
Visible Emission From Shaker Visible Emission From Discharge Conveyor System				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.





Inspector: Stalenu				
Date of Inspection:	Jai 12			
Shift: 1 st Shift or 2 nd Sh	and the same of th	me: 0 0500		
Junit	Visual Inspection <u>NOR</u> MAL or ABNORMAL		Comments	
Visible Emission From Shaker	Nol	- Proce	Down Cour	
Visible Emission From Discharge Conveyor System	Nor	3 personale.	d	

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Inspector:				
Date of Inspection:	* ,			
Shift: 1 st Shift or 2 ^{na} Sh	nift 2ND Ti	me: 5100		
Unit	Visual Inspection <u>NORMAL</u> or ABNORMAL		Comments	
Visible Emission From Shaker	NOR	** is incomplete to particular and the professional of the professional development with the professional development of the p		·
Visible Emission From Discharge Conveyor System	NOR	han generation or any or a		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIDEL LIMISSION NOTA	(110140		-	
Inspector:				
Date of Inspection:	* 1	· · · · · · · · · · · · · · · · · · ·	,	
Shift: 1 st Shift or 2 ^{na} Sh	nift .	Time:		
Visible Emission From Shaker	Visual Inspection <u>NOR</u> MAL or ABNORMAL		Comments	
Visible Emission From Discharge Conveyor System				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			-	
Inspector:	ptin				
Date of Inspection: 2/25/	/ <u>}</u>				
Shift: 1 st Shift or 2 nd Sh		me: 500 AM		-	
Letter Unit	Visual		Comments		•
	Inspection <u>NOR</u> MAL				:
	or ABNORMAL			<u> </u>	
Visible Emission From Shaker	Nov				
Visible Emission From					
Discharge Conveyor System	Nor				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATION	NS			
Inspector: Rick PA	Lone		,	
Date of Inspection: 2/25	112			
Shift: 1 st Shift or 2 nd Shift	and Tir	me: 5:00 AM		
	Visual Inspection <u>NOR</u> MAL Or ABNORMAL		Comments	
	NOR			
Visible Emission From Discharge Conveyor System	Vor	The state of the s		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS		_	-
Inspector: Ted Con	oten.		,	
Date of Inspection: 2/26	Mizi			
Shift: 1 st Shift or (2 nd)Sh	lift Ti	me: .560 AM		
- Junit	Visual		Comments	
	Inspection NORMAL			
	or ABNORMAL			
Visible Emission From Shaker	Nor		general and the second control of the second	
Visible Emission From				
Discharge Conveyor System	Nor		gergiggymalikiringsgeski ^{ng} halide ^{hama} gammanip _{halid} gamm- _{kalum} , .	


- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Inspector;			
Date of Inspection:		-	
Shift: 1 st Shift or 2 nd Shift	Time:	-	
Unif Visual Inspection MORMA Or ABNORM		Comments	
Visible Emission From Shaker			
Visible Emission From Discharge Conveyor System			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Inspector:				·
Date of Inspection:	* ,			
Shift: 1 st Shift or 2 nd Sh	ift Ti	me:		•
Visible Emission From Shaker	Visual Inspection <u>NoR</u> MAL Or ABNORMAL		Comments	
Visible Emission From Discharge Conveyor System				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.



AIGIDEE FINIOGICIA HOTA	110110		1	
Inspector:				
Date of Inspection:	*)			
Shift: 1 st Shift or 2 nd Sh	ift 7	Гіте:		
Unit Visible Emission From Shaker	Visual Inspection <u>NOR</u> MAL or AB <u>N</u> ORMAL		Comments	
	Nor	·		
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			-	
Inspector: Rick PAC	org				
Date of Inspection:	1 / 2 mm				
Shift: 1 st Shift or 2 nd Sh	ift Ti	me: 5000 AM			
- Unit	Visual		Gomments		
	Inspection <u>NOR</u> MAL or ABNORMAL				
Visible Emission From Shaker	ABNORWAL		·		
	NUK	- and conference takes except and the production and the first and the f			
Visible Emission From Discharge Conveyor System	NOR	graphic designation of the second of the sec			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.